

사 진 자 료



<낙숫물이 기단 외부로 떨어짐>



<낙숫물이 기단 내부로 떨어져 기둥 하부 부식>



<빗물받이 물 홈통 설치 사례>