

(붙임)

사 진 자 료



<기와 교체 작업 전(문화재자료 제46호 신송곶장군유허비)>



<기와 교체 작업 후(문화재자료 제46호 신송곶장군유허비)>



<내림마루 보수 전(비지정문화재 척침재)>



<내림마루 보수 후(비지정문화재 척침재)>



<담장과구토 보수 전(문화재자료 제27호 현풍향교대성전)>



<담장과구토 보수 후(문화재자료 제27호 현풍향교대성전)>