

(붙임 2)

사 진 자 료



<안동 하회마을 내 토석담장 무너짐>



<구 목포 일본영사관 천정 누수>



<고창 선운사 대웅전 내림마루 기와 탈락>



<해남 윤씨 녹우당 겹처마 일부 파손>