

**사 진 자 료**



<상주 두곡리 뽕나무 나뭇가지 훼손>



<안동 병산서원 기와탈락>



<안동 하회마을 염행당고택 담장붕괴>



<고창 선운사 대웅전 누수(지붕부위 꺼짐)>