

사 진 자 료

기통 번호	1	2	3	4	5	6	평균	최대-최소 차이
2013년 조사값	6,047	6,152	6,075	6,165	6,046	5,961	5,494.1	204
2019년 조사값	6,000	6,089	6,056	6,092	6,095	6,027	5,482.6	95
2013-2019 비교	-47	-63	-19	-73	+49	+66		

사각골 지점 레벨 실측 데이터


기통번호	1	2	3	4	5	6	평균	최대-최소 차이
2013년 조사값	5,674	5,778	5,771	5,769	5,688	5,598	5,184.4	180
2019년 조사값	5,676	5,755	5,736	5,757	5,757	5,709	5,203.3	81
2013-2019 비교	-2	-23	-35	-12	+69	+111		

추녀골 지점 레벨 실측 데이터



황원정 변위 추정 개념도

[해체 전 실측조사 결과 건물 변위 확인]



[전기비저항조사 결과]



[출처:러시아 베베르공사(1891~1901추정)]



[경복궁 향원정 절병통 현황]



[경복궁 향원정 내부 가새 및 보강목 설치]



[섬돌레석축 하부 목지정(횡목, 종목)현황]



[온돌 발굴조사 현황]



[향원정 중앙부 성토층 현황]



[아궁이 현황]



[아궁이 천장석(길이90cm×너비75cm×두께20cm) 노출 현황]



[배연구 입구 노출 현황]



[연도 및 주변 초반 노출 양상]



[연도 노출 양상]



[초반 균열 생성 양상]



[연도 마감부 노출 양상]



[경복궁 향원정 홍보관 전경]