

(붙임 3)

사 진 자 료



< 낙서로 훼손된 경복궁 담장 복구 대책 논의하는 최응천 문화재청장('23.12.16.) >



< 낙서 제거 위한 미세 블라스팅 작업 모습('23.12.19.) >



< 낙서 제거 위한 레이저클리닝 모습('23.12.17.) >



< 낙서 제거 위한 래커 시너 도포 모습('23.12.17.) >



< 공능에 설치된 낙서금지 안내배너 >